

QUESTIONS and ANSWERS

Tender Ref No	CTIA7298/2023/RFP
Tender Description	Refurbishment of Terminal Roofs within a Period of 12 Months at Cape Town International Airport (CTIA)

IMPORTANT: Tenderers are required to acknowledge this Q&A in their tender submission in the table for RECORD OF ADDENDA TO TENDER DOCUMENTS (Form A2)

NO.	TENDERER QUESTION/QUERY	ACSA RESPONSE
1	CIDB 5GB requirements. Are we allowed to tender if we have a 9SL and 7ME CIDB Grading. GB grading is understood as general building works.	Only CIDB grading of 5GB or higher is acceptable for this tender.
2	Section 3 – P&G Does not make allowance for Fix and time related P&G items. Should this be included in all the rates in section 1 and section 2?	Yes
3	Scaffolding access what Tonnage will be required. Where do we include this in the BOQ?	Part of Site Establishment
4	Will the inside of the terminal be barricaded during execution phase (who is responsible for it). IE no public access allowed.	ACSA - CTIA
5	Is there tie in points for lifeline on the roof?	Yes
6	Please provide detail of the environment professional required on this project.	All works must be done within the necessary legislation. There is no line item to be priced for an environmental professional. ACSA has an environmental division which will guide accordingly.

M Gounden

ACSA - SCM